2016 ANNUAL INSPECTION OF CCR LANDFILL BY QUALIFIED PROFESSIONAL ENGINEER 40 CFR 257.84

FACILITY INFORMATION		
Facility Name/ Address	La Cygne Generating Station / 25166 East 2200 Road La Cygne, Kansas 66040	
Owner Name	Kansas City Power & Light Company	
CCR Unit	CCR Landfill	
Inspection Date	October 25, 2016	

ANNUAL CCR UNIT INSPECTION REPORT		
Rule	Inspection Results	
(b)(1)(i) – Review of available information regarding the status and condition of the CCR unit.	Seven-day inspection reports dated 01/05/16 through 10/25/16 prepared by a qualified person were reviewed. No issues of concern with the CCR unit were noted.	
(b)(1)(ii) – Visual inspection of the CCR unit to identify signs of distress or malfunction.	Visual inspection by a qualified professional engineer was made on October 25, 2016. No signs of distress or malfunction were noted.	
(b)(2)(i) – Changes in geometry of the structure since the previous annual inspection.	A perimeter ditch and berm were added for storm water run- on and run-off control.	
(b)(2)(ii) – Approximate volume of CCR contained in the unit at the time of the inspection.	Approximately 6.6 million cubic yards ¹ .	
(b)(2)(iii) – Appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit.	None. An inspection made in person found no appearances of an actual or potential structural weakness of the CCR unit or existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit.	
(b)(2)(iv) – Other change(s) which may have affected the stability or operation of the CCR unit since the previous annual inspection.	None.	

QUALIFIED PROFESSIONAL ENGINEER		
Prepared by	Brian D. Linnan	
Date	January 6, 2017	
Signature	Bruhann	



1. Volume calculations were completed by AECOM using an updated topographic survey dated June 23, 2016 by Tukuh Technologies. Volume includes CCR placement through June 23, 2016.